



Rail Management Hot Topics and Developments

Brian Whitney – Engineering Expert Track & S&C

PWI West of England Section

brian.whitney@networkrail.co.uk 07990 533 768



Providing technical leadership


Hatfield - 12.23 Tuesday 17 October 2000




Hatfield - 12.23 Tuesday 17 October 2000



Broken Rail History - Long term Trend



Broken Rail Controls since 2000



A long term continuous improvement plan based on improved monitoring and inspection, data driven analysis and understanding of root cause coupled with a large number of initiatives, developments, improved processes, updated standards and improvements to rail management.

Unfortunately there were very few quick fixes and no magic wands.

The quicker wins have already been had and further reductions become increasingly more difficult to realise



Hatfield - 12.23 Tuesday 17 October 2000




Broken Rail, RCF – 2nd January 2019 NAI1, 2100, 2m 440yds





Broken Rail, RCF, 12th May 2020, VTB2, 1100, 19m 1078yds


At 0635, DP track circuit failed on the Up Quarry Line, between Redhill Tunnel and Quarry Tunnel, fortunately only a single break.




Broken Rail RCF, 12th May 2020, VTB2, 1100, 19m 1078yds

ELR: Track Id: From Date: End Date: Start Mile Post: End Mile Post: Display Type:

Generate Chart



Broken Rails By Type 2013 – 2018 Top 15 by Cause




Rail Foot Failures Account For Around 50% Of Annual Breaks



There has been a previous rail break at this location and the majority of rail breaks in the rail foot are caused by poor support conditions



Could this be found by UT?




20-04-17, LEC1 1100, 29m 700yds
Northchurch, 1980, 113A rail.
Break initiated from the rail foot due to high dynamic loading from voiding
sleepers and poor support conditions
No significant defect to detect by inspection.
Need to manage the conditions where this risk exists



LEC1 1100 29m 700yds Northchurch

Dip in measured geometry trace



High contact stresses and an aggressive environment.


Static wheel loads from 60 to 125 kN on a small contact patch (5 pence)



125kN on 250mm² is around 500N/mm² without any lateral or longitudinal forces or the dynamic effects of the wheel in motion due to track and wheel irregularities



Severe RCF with branched transverse defect



Visual Inspection and Manual Measurement of Surface Length






**INSPECTOR
SPERRY®**

Surface Crack RSU




10 probes providing full
coverage across rail head



Intelligent RSU with built in
digital processing

RDMS Eddy Current Upgrade



The screenshot shows the RDMS Eddy Current Upgrade interface. The top navigation bar includes links for Dashboard, Suspect, Defect, Broken Rail, RCF, EC RCF, PLPR, Reports, Help, and Logout. The main content area displays two tables: Defects and EC RCF.

Defects Table:


Region	TNC	Disp.	Overdue	Due This Week	Due In 2 Weeks	Due In 3 Weeks	Due In Week > 3
Anglia	163	82	154	48	57	46	2048
East Midlands	77	32	53	5	10	5	319
Kent	61	8	49	29	15	23	376
LNE	181	67	124	23	42	34	1823
LNW North	84	39	78	35	57	69	2269
LNW South	50	43	77	18	23	29	933
Scotland	111	17	93	52	49	70	1521
Sussex	62	2	18	20	31	16	275
Wales	15		2	3	8	9	546
Wessex	104	11	164	20	42	14	533
Western Thames Valley	139	19	9	13	23	24	478
Western West	11		2	7	4	9	440

EC RCF Table:

Region	Volume by Severity					Overdue for Inspection					Non compliant Inspection					Planned Remediation					UnPlanned Remediation					Notifications					
	VS	S	H	M	L	VS	S	H	M	L	VS	S	H	M	L	VS	S	H	M	L	VS	S	H	M	L	VS	S	H	M	L	
Anglia	2179	355	587	1616	2005	124	21	43	140	116	2010	324	528	1453	1869							2179	355	587	1616	2005					
East Midlands	1086	174	266	679	604	223	31	57	140	100	822	141	201	516	476							1086	174	266	679	604					
Kent	1029	215	339	843	973	153	40	62	172	147	812	162	255	592	766							1029	215	339	843	973					
LNE	3191	471	723	2176	1886	277	38	77	157	179	2817	422	631	1985	1678							3191	471	723	2176	1886					
LNW North	1753	277	463	1035	1227	330	47	78	106	130	1383	229	377	917	1088							1753	277	463	1035	1227					
LNW South	3030	413	660	1846	2611	263	43	65	152	134	2692	353	551	1610	2322							3030	413	660	1846	2611					
Scotland	2328	422	631	1586	1559	217	41	98	281	148	2016	356	503	1206	1212							2328	422	631	1586	1559					
Sussex	1266	200	333	828	1334	60	16	22	43	38	1162	180	303	757	1251							1266	200	333	828	1334					
Wales	1040	180	228	567	758	200	28	45	113	107	821	149	179	451	641							1040	180	228	567	758					

Contains commands for working with the selected items.

[RDMS Link](#)



[Link to SDMS](#)




Run on Run Analysis, Repeatability, Consistency




[Link to SDMS](#)



Rail Profile (Sidewear) – Data Issues Left and Right rail reversal



Remediation through Milling



Rail Milling Profile Management

- ▶ Two Contracts agreed,
 - Schweerbau HSM 3 year service starting 07-2018
 - Linsinger Duplex procurement delivery March 2021
- ▶ Delivering rail re-profiling & defect removal = increased rail life




Sperry B Scan Flaw Detector



- Upgrade of existing equipment using original frame and roller search unit
- Output mirrors B Scan output from UTUs
- Can be used in A Scan mode replicating the current equipment
- B Scan equipment provides full recording of all test data
- Reduced weight as no additional flaw detector required
- Can be used with range of hand probes
- Increased battery life
- Built in GPS and encoders for accurate location
- Menu driven screen for more accurate in built defect reporting



UX9 (current UK UTU Fleet)



Ultrasonic RSUs

Switzerland & Germany (SPF101)


UK / Germany (SRS200)

Core Transducers

- 0° Horizontals such as head and web splits
- 37° Bolthole cracks and base cracks
- 70° Transverse defects in rail head

Additional Transducers

- VSH Vertical Split Head / Shear Break
- X-Fire® Improved Transverse Detection under RCF





Note: In North America both VSH/ Sidelookers and X-Fire® are essential


***Porthkerry Derailment Down Vale of Glamorgan Line (VOG)
2nd October 2014***



VSH / SideLooker RSU



Vertical Split Heads




UX8 RSU

New for 2019

Inlet /outlet ports for cooling
and heating RSU

Prototype UX8 already tested over SBB
calibration track. 4500Hz PRF

Will be deployed in Australia in Oct 2019



8 Channel Ultrasonic Highspeed RSU – Temperature Control
(2019)

Confidential and proprietary information, Sperry 2019©




Synchronised Eddy Current and Ultrasonic BScan

Severity

Crack depth

Analyst making decisions
based on combined
technologies.
(1950 only)





**INSPECTOR
SPERRY®**

Vision System



Vision Hardware



Vision image is accessible to analyst
from BScan



BScan Lite Dual Rail Inspection System DRIS


New for 2020



- 2 x UX9 RSU (Inspects Both Rails in One Pass)
- Light Weight Design Construction (Total = 47 kg)
- A Scan and B Scan Display Modes (Tablet)
- B-Scan Lite H/W and S/W Compatibility (Limited Operator Training Transfer from B-Scan Lite W.Stick)
- Offers Real-time and Offline Data Analysis
- Two Supply Configurations (Complete System or Mech and Elect + 2 x Existing NR W.Stick RSU)

Hand-Held verification

Multiple trials carried out to demonstrate the functionality



Combining Data – Better Information

TME	TSM	ELR	Track ID	Mile	Yard	Chain	Rail Side	Speed	Measurement Date	Rail Section	Gauge Side Wear	Gauge Side Step	Field Side Wear	Field Side Step	Head Width	Head Width Remaining	Combined Side Step	Vertical Wear	Estimated Rail Depth	Fishplate Clearance	Lip Width	Inclination	Deviation	Gauge Face Remaining	Web Width	70mm - Head Width	GPS - Lat	GPS - Lon
TME Swansea a	SWM2	1100	250	728	33.1	L	75	02-Aug-18	Br109fb	-0.2	18	0.4	17	69.8	17.8	35	4.0	154.8	10.0	0.0	-0.8	19.2	15.6145	0.2300	51.83853912	-4.431075096		
TME Swansea a	SWM2	1100	250	728	33.1	R	75	02-Aug-18	Br109fb	0.0	18	-1.9	18	71.9	19.9	36	4.6	154.3	9.3	0.1	1.0	24.3	17.4868	-1.9090	51.83853912	-4.431075096		
TME Swansea a	SWM2	1100	250	731	33.2	L	75	02-Aug-18	Br109fb	0.3	17	-0.2	18	69.9	17.9	35	3.9	155.0	9.7	0.0	-0.3	19.2	15.7142	0.0630	51.83852005	-4.431099892		
TME Swansea a	SWM2	1100	250	731	33.2	R	75	02-Aug-18	Br109fb	-0.4	18	-1.5	18	71.9	19.9	36	5.9	153.0	8.4	0.0	0.5	21.8	17.3489	-1.9310	51.83852005	-4.431099892		
TME Swansea a	SWM2	1100	250	735	33.4	R	75	02-Aug-18	Br109fb	-0.5	18	-1.5	18	72.0	20.0	36	6.1	152.7	8.2	0.0	0.9	21.8	17.4065	-1.9780	51.83850861	-4.431152821		
TME Swansea a	SWM2	1100	250	739	33.6	L	75	02-Aug-18	Bs113afb	-0.5	18	0.0	17	70.5	18.5	35	3.4	155.4	10.9		-0.5	24.7	20.5534	-0.5110	51.83848953	-4.431206226		



Confirmed during verification as a 1B defect – 20mph ESR, remove within 7 days



Combinations of Defects – Increased Risk



Factors;

Known wet spot in tunnel

- Significant head and foot loss due to corrosion (rail depth recorded as 143 to 146mm, loss of around 15mm compared to a new rail, below minimum rail depth)
- Significant dip angle in plain line present for a long time (repeated dip angle in plain line 27 mrad repeated 36 times) voiding / localised head loss? Fatigue
- 1989 113A R220 rail – no coating
- 90 mph, Track Cat 2, EMGTPA
- 2 sections identified with significant reduction in rail depth / localised head loss
- Dispensation timescales, risks and mitigation?
- Consider other factors when assigning MACs and determining action timescales – dynamic loading from dip, poor support conditions, rail strength

Site Name	ELR	Track	Start Mile	End Mile	Rail	Description	MAC	Date Found	Due Date	Status	Track Cat	Line Speed	Defect Comment
Disley Tunnel	NMC1	1100	174.0760	174.0770	Right	208 - Insufficient rail depth	3T	25-May-18	21-May-21	Open	2	90	Remove rail in 3 years
Disley Tunnel	NMC1	1100	174.0750	174.0850	Right	208 - Insufficient rail depth	3L	24-May-16	21-May-19(D)	Open	3	90	Under minimum permitted rail depth

Combinations of Defects – Increased Risk



- Identified as a cracked rail by PLPR inspection 2nd September 2018
- Rail has fractured up from the rail foot and propagated along the top of the web for approximately 300mm with a significant risk of a section of the rail head breaking out
- Minimum rail depth exceeded at one location and entered into RDMS as a 3L (52 week defect), original removal date May 2017 dispensed until May 2019

Minimum rail depth reached and rail entered into RDMS in May 2018 as a three year defect due May 2021.

Replace the rail **within 3 years** or replace the rail in 3 years time?

Are selected **Minimum Action Codes** appropriate?


Table 2 – Minimum rail depths		
Rail section	Minimum depth (no sidewear) mm	Minimum depth (sideworn) mm
CEN60 E1 and E2 flat bottom plain line	158	158 + L
CEN60 E1 and E2 flat bottom S&C	162	162 + L
109 / 110A / CEN56 (113A) flat bottom	145	145 + L
98 flat bottom / 95 and 97.5 bullhead	131	131 + L
85 bullhead	127	127 + L
Note: $L = 9 - 0.5S$ Where L is the lateral head loss and S is the NR4 standard step gauge reading.		

3.3 Action for rail at or below minimum permitted depth


Replace the rail within three years of the minimum depth specified in Table 2 being reached.



Combining Data – Rail Depth from UTUs



Combining Data – Rail Depth from UTUs




Guided Wave Ultrasonics - G – Scan Mk 2



Second generation longitudinal wave ultrasonic equipment now being trialled on LNE to screen level crossings for corrosion and potential loss of rail section.

System using a longitudinal wave and mode transformation caused by any loss of rail section anywhere in the rail rather than conventional ultrasonics which works based on a reflected signal from a specific defect or surface.

Intelligent Infrastructure Project, II, eDST

	Work Package Description	Target Reduction
Work Package A	- Track Geometry & Cyclic Top Defect Review Page - PLPR Defect Review Page - Maintenance Dashboard & Landing Page - Intervention Support & Planning Page - Track Quality & Trace Review Page	 Manual Basic Visual Inspections
Work Package B	- Rail Management Defect Review Page: - Rail Depth - Side Wear - Rail Profile Faults - Rolling Contact Fatigue - Rail Flaws - IRJs - Ballast Profile - Work Specification	 Insulated Rail Joint Inspections Track Geometry Measurements Manual Rail Depth Inspections Manual Ultrasonic Testing Rolling Contact Fatigue Testing Side-wear Inspections
Work Package C	- Structure Gauging - Supervisor's Inspection App - Rail Stress Data - Analytics & Mobile Inspection App	 Datum Plate Surveys

- The automatic identification of issues presented in the EDST
- Ability to predict where issues will occur
- Ability to prioritise workbanks
- Longer lead time to determine the desired intervention allowing for the best intervention to be selected
- Ability to make risk-based inspections
- Access to historic data across the network
- Consolidation of data for each issue in one place (EDST)

- Ability to view the location of faults through a mobile app
- Ability to view the details of planned work through mobile devices whilst at risk sites
- Ability to identify work which has been done previously and also not yet been completed



It's not just broken and defective rails



Understanding track buckle risk

Current research activities looking at a number of areas

Modelling with University of Southampton to better understand risks and to carry out a sensitivity analysis to look at potential to review hot weather management requirements in mod 14.

Model considers a range of factors and their contribution to buckling risk.

SFT measurement

Current research activities looking at non intrusive measurement of rail stress and SFT

University of Sheffield research development to measure SFT using ultrasonic time of flight technology without the need to unclip rail.

Initial site trials at Grange sidings today in conjunction with the induction welding approval programme.



Induction Welding

Rail ends are then aligned and pushed together and held under pressure.

Simple induction coil placed around the ends of each rail.

Controlled heating of the rail ends achieved by varying frequency and power input to heat the rail ends to just below melting point.

Heating cycle typically takes around 3 to 3 ½ minutes

Temperatures can be very accurately controlled to achieve precisely the correct rail end temperature across the entire rail section.

Careful control required due to the variable thicknesses of the rail section with the head requiring more heat input than the thinner section web and foot.

Rails are then forged together expelling the rail end material forming an upset around the weld.

The heating coil is then moved to one side and a stripping die fastened around the rail.

Stripping die is then pushed along the rail to remove the excess upset material from all round the weld.

Weld is then allowed to cool and finished by profile grinding around the head of the rail.

Grinding carried out to achieve the high degree of accuracy (+0.4 / -0.0 mm) flatness across the weld.



Initial Test Results


Sections through the weld machined and hardness tested from the parent rail through the weld and back into the parent rail.

Initial welds show a slightly increased but very constant level of hardness compared to the parent rail with only slight drops in hardness in the heat affected zones

Hardness survey shows no evidence of material changes around the weld fusion area.

Metallographic examination of the microstructure shows no fusion line with a homogenous structure throughout the weld.

No weld line visible with ends fully fused





Initial Test Results

Bend tests carried out to compare the weld performance to an un-welded section of plain rail.

Welds achieving virtually the same strength as the plain rail.

Rails distorted permanently rather than breaking along the weld line.



Bend tests indicate a weld strength over 150 tonnes for 56 E2 rail



The Competition

Conventional alumino-thermic welding;

Highly portable – minimal plant required

Two man team required

Now very reliable with failure rates of around 1 in 50,000

Able to fill a gap between the rail ends without consuming a length of rail like forged welds

Easily scalable by using more welding teams as required

Typical weld time around 2 hours plus finishing time



Conventional flash butt welding;


Significant plant required to provide very high levels of electrical power required to heat the rails using resistance heating (60,000 amps)

Typical road rail vehicle around 30 tonnes, welding head large typically around 3 tonnes

Very reliable with failure rates of around 1 in 100,000

Flash butt welding consumes a length of rail during forging

Typical weld time around 8 minutes plus finishing time



Design for Reliability – University of Huddersfield

Developed profile – result of parametric evaluation of a matrix of cross-sectional designs

Key features compared to 60E2:

Head & foot width, rail height, crown profile, web thickness, foot tip thickness maintained – no implications for gauge, sleeper seat, and fastenings


Head height increased 50 % - area by ~63 %

Foot area increased by 38 %

Web area reduced by 31 %


Overall increase concentrated in the head and centre of the foot, (part affecting performance and life span)

Location of neutral axis unaltered




Implications of Design for Rail Wear


- Worn profiles of the reference 60E2



60E2 WV14




60E2 WVL14




$$W = W1 + W2$$


- Worn profiles of the designed HDFTO




HDFTO WV14




HDFTO WV28



HDFTO WVL14



HDFTO WVL28





HDFTO WVL35

Record Low Numbers of Broken Rails



Still a fair comment?



Whilst we had 93 breaks in 2018 – 2019 and 107 in 2019 – 2020 we have still had two derailments due to broken rails in the last six years.

Unfortunately rails rarely fail safely and more traffic, increased tonnages, higher speeds and modern axle counter signalling systems increase the risk of trains continuing to run over broken rails before they are detected

We have not eliminated the risk, we have reduced it but a level of risk still remains.

Future targets 50 x 30 (50 breaks / year by 2030), expectations and PPF

Increased traffic volumes? Reduced access? Modern vehicles and increased RCF?



Many thanks for your time and the opportunity to present

Any Questions?



**Technical
Authority**



Providing technical leadership